

[REDACTED]

D/M/OSA

[REDACTED]

6 FEB 67

SECRET

ROUTING	
1	D/M/OSA
2	D/M/OSA
3	D/O/OSA
4	IDEA/OSA
5	ORD
6	RE/OSA
7	
8	
PRIORITY	
DEFERRED	PRIORITY
ROUTINE	OPERATIONAL IMMEDIATE

16-12

06:51

OPS-1-10

TO SECRET INFO 6 21 32 2 CITE [REDACTED]

PRIORITY [REDACTED] 25X1A

25X1A

IDEALIST [REDACTED] 25X1A

25X1A

[REDACTED]

25X1A

1. [REDACTED] FLIGHTS SUSPENDED PENDING FURTHER

EVALUATION OF FLIGHT SAFETY IMPLICATIONS NOTED DURING THE 4 FEBRUARY FLIGHT.

25X1A

2. FOR [REDACTED] INTENDS

PROCEED FROM [REDACTED] TO YOUR FACILITY TO DISCUSS

25X1A

ENGINEERING "FIXES" ON 6 FEB 67. FOR YOUR INFO, [REDACTED]

25X1

IS CONDUCTING PRESSURE CHAMBER TESTS TO DETERMINE WHETHER

PRESSURE RELIEF HOLES COVERED BY PAINT CONTRIBUTED TO

PREMATURE CHUTE DEPLOYMENT. REQUEST [REDACTED] INVESTIGATE

25X1A

WHETHER POD COULD HAVE SLID AFT AND ALLOWED [REDACTED]

25X1A

TO INITIATE. 25X1A

3. HQTRS WILL AWAIT [REDACTED] AND [REDACTED] EVALUATIONS

25X1

BEFORE PERFORMING ANY FURTHER [REDACTED] FLIGHTS.

25X1A

END OF MESSAGE

IDEA/O/OSA/ [REDACTED]

25X1A

[REDACTED]

COORDINATING OFFICER

SECRET

[REDACTED]

D/O/OSA

RELEASING OFFICER

D/M/OSA

AUTHENTICATING OFFICER

25X1A

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.